

**What is in the V15 Processor Motion bundle?**

Below is a listing of all the firmware that is included in V15 Processor Motion 10-23-09.zip.

- Bundle rebuilt with ControlFLASH v8.00.017 to prevent RSLogix 5000 v16 software from auto flashing a 1768-L4x Series B Controller with older 1768-L4x Series A firmware.
- Firmware revisions haven't changed since last bundle.

To find out what was changed in these product revisions, please open the specific PDF file that is located next to each product on the download page.

Catalog Number	Revision
1756-HYD02	15.1
1756-L55	15.5.32
1756-L60M03SE	15.4.31
1756-L61	15.4.31
1756-L62	15.4.31
1756-L63	15.4.31
1756-M02AE	15.1
1756M02AS	15.1
1756-M03SE	15.32
1756-M08SE	15.32
1756-M16SE	15.32
1768-L43 Series A	15.7.12
1768-M04SE	15.37
1769-L31	15.4.31
1769-L32C	15.4.31
1769-L32E	15.4.31
1769-L35CR	15.4.31
1769-L35E	15.4.31
1794-L34	15.6.1
DriveLogix5730	15.3.24